L Number	Hits	Search Text	DB	Tim stamp
- Number	13	optoelectronic and herm ti and (package	USPAT;	2004/05/20
		r pa kaging) and frame and feedthrough	US-PGPUB;	14:51
		i pa kaying, and frame and feedinough	EPO; JPO;	14.51
			DERWENT;	
			IBM_TDB	
_	2	optoelectronic and hermetic and (package	USPAT;	2004/05/20
- 	_	or packaging) and frame and feedthrough	US-PGPUB;	14:51
		and ground	EPO; JPO;	14.51
			DERWENT;	
			IBM_TDB	
	46	hermetic and (package or packaging) and	USPAT;	2004/05/20
	70	frame and feedthrough and ground	US-PGPUB;	14:52
		Traine and feedthrough and ground	EPO; JPO;	14:52
			DERWENT;	
			IBM_TDB	
_	15	hermetic.clm. and (package or packaging)	_	2004/05/20
`	13	and frame and feedthrough and ground	USPAT;	
		and frame and feedthrough and ground	US-PGPUB;	14:52
			EPO; JPO;	
			DERWENT;	
	9	homosia alm and (nackana an	IBM_TDB	2004/05/00
'	9	hermetic.clm. and (package or	USPAT;	2004/05/20
		packaging).clm. and frame and feedthrough	US-PGPUB;	14:52
		and ground	EPO; JPO;	
			DERWENT;	
		h	IBM_TDB	0004/05/00
'	4	hermetic.clm. and (package or	USPAT;	2004/05/20
		packaging).clm. and frame.clm. and	US-PGPUB;	14:52
		feedthrough and ground	EPO; JPO;	
			DERWENT;	
	•	h	IBM_TDB	0004/07/00
·	3	hermetic.clm. and (package or	USPAT;	2004/05/20
		packaging).clm. and frame.clm. and	US-PGPUB;	14:52
Ì		feedthrough.clm. and ground	EPO; JPO;	
			DERWENT;	
	3	hammatic also and to also as	IBM_TDB	0004/05/00
·	3	hermetic.clm. and (package or	USPAT;	2004/05/20
		packaging).clm. and frame.clm. and	US-PGPUB;	14:53
		feedthrough.clm. and ground.clm.	EPO; JPO;	
			DERWENT;	
	_	(homostic on homostically) /furness	IBM_TDB	0004/05/00
	5	(hermetic or hermetically) same (frame or	USPAT;	2004/05/20
		case or casing) same (feedthrough) same	US-PGPUB;	14:54
		(bond or bonding or wirebond) same ground	EPO; JPO;	
		same (wire or wiring)	DERWENT;	
	_	//h was 4: - 11-3 /6	IBM_TDB	2004/25/22
'	1	((h rmeti r hermetically) same (frame or	USPAT;	2004/05/20
		case reasing) same (feedthr ugh) same	US-P PUB;	14:54
		(b nd r b nding or wirebond) sam ground	EPO; JPO;	
		same (wir r wiring)).clm.	DERWENT; IBM_TDB	

•	84	(h rmetic near10 feedthrough).clm.	USPAT;	2004/05/20
			US-PGPUB;	14:55
	l		EPO; JPO;	
			DERWENT;	
			IBM_TDB	
-	34	(hermetic near10 f dthr ugh). Im. and	USPAT;	2004/05/20
		hermetic.ab.	US-PGPUB;	14:55
			EPO; JPO;	
			DERWENT;	
			IBM_TDB	
-	31	(hermetic near10 feedthrough).clm. and	USPAT;	2004/05/20
		hermetic.ab. and feedthrough.ab.	US-PGPUB;	14:55
			EPO; JPO;	
			DERWENT;	
			IBM_TDB	
-	3	(hermetic near10 feedthrough).clm. and	USPAT;	2004/05/20
		hermetic.ab. and feedthrough.ab. and	US-PGPUB;	14:55
		ground.clm.	EPO; JPO;	
			DERWENT;	
			IBM_TDB	
-	0	(hermetic near10 (package or packaging)	USPAT;	2004/05/20
		near10 feedthrough).clm. and hermetic.ab.	US-PGPUB;	14:57
		and feedthrough.ab. and ground.clm.	EPO; JPO;	
			DERWENT;	
			IBM_TDB	
-	0	(hermetic near20 (package or packaging)	USPAT;	2004/05/20
		near20 feedthrough).clm. and hermetic.ab.	US-PGPUB;	14:56
		and feedthrough.ab. and ground.clm.	EPO; JPO;	
			DERWENT;	
			IBM_TDB	
-	4	(hermetic near20 (package or packaging)	USPAT;	2004/05/20
		near20 feedthrough).clm.	US-PGPUB;	14:56
			EPO; JPO;	
			DERWENT;	
			IBM_TDB	
-	2	(hermetic same feedthrough same (wire or	USPAT;	2004/05/20
		wiring) same ground).clm.	US-PGPUB;	14:58
	Ì		EPO; JPO;	
			DERWENT;	
			IBM_TDB	
-	219	(feedthrough same (wire or wiring) same	USPAT;	2004/05/20
		ground)	US-PGPUB;	14:59
			EPO; JPO;	
			DERWENT;	
			IBM_TDB	
-	21	(feedthrough same (bond or bonding or	USPAT;	2004/05/20
		bonded or wirebond) same (wire or wiring)	US-PGPUB;	15:09
		same gr und)	EPO; JPO;	
			DERWENT;	
			IBM_TDB	

•	2	((feedthrough adj assembly) same (b nd r bonding or bonded or wir b nd) same (wire r wiring) same ground)	USPAT; US-PGPUB; EPO; JPO;	2004/05/20 15:10
			DERWENT; IBM_TDB	
-	1	((fe dthrough) same (bond r b nding r bonded or wirebond) same (wire or wiring)	USPAT; US-PGPUB;	2004/05/20 15:10
		same ground).clm.	EPO; JPO; DERWENT; IBM_TDB	
-	13	((feedthrough) same (bond or bonding or	USPAT;	2004/05/20
		bonded or wirebond) same (wire or wiring) same ground) and hermetic	US-PGPUB; EPO; JPO; DERWENT; IBM_TDB	15:11
-	7	((feedthrough) same (bond or bonding or	USPAT;	2004/05/20
		bonded or wirebond) same (wire or wiring) same ground) and hermetic and	US-PGPUB;	15:12
		(feedthrough near10 ground)	EPO; JPO; DERWENT; IBM_TDB	
-	84	(hermetic adj package).clm.	USPAT;	2004/05/20
			US-PGPUB; EPO; JPO; DERWENT;	15:12
			IBM_TDB	
-	34	(hermetic adj package).clm. and (hermetic adj package).ab.	USPAT; US-PGPUB;	2004/05/20 15:13
	:		EPO; JPO; DERWENT;	
-	2	(hermetic adj package).clm. and (hermetic	IBM_TDB USPAT;	2004/05/20
		adj package).ab. and feedthrough.clm.	US-PGPUB; EPO; JPO; DERWENT;	15:13
	_		IBM_TDB	
-	2	(hermetic).clm. and (hermetic adj package).ab. and feedthrough.clm.	USPAT; US-PGPUB;	2004/05/20 15:13
			EPO; JPO; DERWENT;	
			IBM_TDB	
-	56	(hermetic).clm. and (hermetic).ab. and feedthrough.clm.	USPAT; US-PGPUB;	2004/05/20 15:13
			EPO; JPO; DERWENT;	
-	6	(hermetic).clm. and (hermetic).ab. and	IBM_TDB USPAT;	2004/05/20
		feedthrough.clm. and (package or	US-PGPUB;	15:14
		packaging).clm.	EPO; JPO;	
			DERWENT;	
	1			1

-	2	(h rmetic). lm. and (hermetic).ab. and	USPAT;	2004/05/20
		feedthrough.clm. and (package r	US-P PUB;	15:15
		packaging).clm. and gr und. lm.	EPO; JPO;	
			DERWENT;	
			IBM_TDB	
	7	(((h rm ti r hermetically) near	USPAT;	2004/05/20
		(packaging or package)) same	US-PGPUB;	15:16
		feedthrough).ti,ab,clm.	EPO; JPO;	
			DERWENT;	
			IBM TDB	